

MARCAS Y MODELOS	CODIGOS BUJÍAS COBRE	CODIGOS BUJÍAS PARA GNC	F 3+1	Luz e.e. mm
ALFA ROMEO				
33 - 1.7 Sport Wagon, QV	C 72 LS3X	C 82 LS	L87	0.8
33 - 1.7 Sprint	C 72 LS3X	C 82 LS	L87	0.8
33 - 1.7 ie	C 72 LS	C 82 LS	L87	0.8
75 - 1.8 ie Scuderia	C 82 LS	C 92 LS	L87	0.8
145 - 1.7 ie 16V	RFC 82 LS	-	F86	0.8
146 - 1.6 ie	C 82 LS	C 92 LS	L87	0.8
155 - 1.7 ie T.Sp	RFC 82 LS	-	F86	0.8
155 - 2.0 ie T.Sp	RFC 82 LS	-	F86	0.8
156 - 1.8 ie T.Sp	RFN 58 LZ	RFC 62 LS	F54	0.8
156 - 2.0 ie T.Sp	RFC 82 LS	-	F86	0.8
164 - 2.0 ie T.Sp	RFC 82 LS	-	F86	0.8
166 - 2.0 ie V6 Turbo	RC 72 LS	RC 82 LS	L87	0.7
AUDI				
A 3 - 1.8 i 20V	RFC 58 LZ3EX	RFC 62 LS	F54	0.9
A 3 - 1.8 T 20V	RFC 58 LZ3EX	RFC 62 LS	F54	0.9
A 4 - 1.8 T 20V	RFC 58 LZ3EX	RFC 62 LS	F54	0.9
A6 - 1.8 T 20V	RFC 58 LZ3EX	RFC 62 LS	F54	0.9
A 6 - 2.4 i V6	RFC 58 LZ3EX	RFC 62 LS	F54	0.9
A 8 - 2.8 i V6 30V	RFC 62 LZ2	RFC 82 LS	F86	0.8
TT - 1.8 T 20V	RFC 58 LZ3EX	RFC 62 LS	F54	0.9
BMW				
Serie 3 - 320 : 2.0 i [E30]	C 52 LS	755 LS	L65	0.7
Serie 3 - 323 : 2.3 i [E21]	C 52 LS	755 LS	L65	0.7
Serie 3 - 323 : 2.5 i 24V [E46]	RFC 58 LZ2E	RFC 62 LS	F54	0.9
Serie 3 - 325 : 2.5 i Touring [E30]	RC 62 LS	755 LS	L65	0.7
Serie 3 - 328 : 2.8 i 24V [E46]	RFC 58 LZ2E	RFC 62 LS	F54	0.9
Serie 5 - 520 : 2.0 i [E28]	RC 52 LZE	755 LS	L65	0.7
Serie 5 - 520 : 2.0 i 24V , Worldline [E39]	RFC 58 LZ2E	RFC 62 LS	F54	0.9
Serie 5 - 523 : 2.5 i 24V [E39]	RFC 58 LZ2E	RFC 62 LS	F54	0.9
Serie 5 - 525 : 2.5 [E12]	C 52 LS	755 LS	L65	0.7
Serie 5 - 525 : 2.5 i [E34]	RC 62 LS	755 LS	L65	0.7
Serie 6 - 635 : 3.4 i [E24]	C 52 LS	755 LS	L65	0.7
Z 3 - 1.9 i 16V	RFC 58 LZ2E	RFC 62 LS	F54	0.9

Z 3 - 2.8 i 24V	RFC 58 LZ2E	RFC 62 LS	F54	0.9
CHEVROLET				
Astra 1,8 , 16V-	RFC 42 LZ2E	RFC 52 LS	F54	-
Astra 1,8 , 8V-	RC 62 LS	RC 72 LS	L65	0,8
Astra 2,0 , 8V-	RC 62 LS	RC 72 LS	L65	0,8
Astra 2,0 , 16V-	RFC 42 LZ2E	RFC 52 LS	F54	-
Chevy, 400, Malibu, Super, Coupé	C 32 LS	755 LS	-	0.8
Corsa EFI y MPFI - 1.4 i GL y 1,6 - 8V	RC 62 LS	RC 72 LS	L65	0,7
Corsa MPFI (1.6 - 16V)	RFC 42 LZ 2E	RFC 52 LS	F54	-
K 180 Opel	C 52 LS	755 LS	L65	0.6
Monza 1.6, 1.8	RC 32 LS	RC 52 LS	-	1,0
Monza 2.0	RC 52 LS	RC 62 LS	L65	0,7
Omega 2.0	RC 52 LS	RC 62 LS	L65	0,7
Omega 3.0	RC 42 S	RC 42 S	-	0,7
Special, Super, Rallye	C 32 LS	755 LS	-	0.8
Suprema 2.0	RC 52 LS	RC 62 LS	L65	0,7
Vectra - MPFI 2.0 - 8V	RC 62 LS	RC 72 LS	L65	0,7
Vectra - MPFI 2.0 - 16V	RFC 42 LZ2E	RFC 52 LS	F54	-
Vectra - MPFI 2,2 - 8V	RC 62 LS	RC 72 LS	L65	0,7
Vectra - MPFI 2,2 - 16V	RFC 42 LZ2E	RFC 52 LS	F54	-
Utilitarios :				
C20	C 32 LS	755 LS	-	1.0
C20, De Luxe 4.1	RC 32 LS	RC 52 LS	-	0,8
FTC 10 Custom, Silverado	C 32 LS	707 LS	-	1.0
Luv 2,3 y 2.5	C 52 LS	755 LS	L65	0,7
Veraneio 4 cil.	RC 52 LS	RC 62 LS	L65	0,9
CITROËN				
2CV, 3CV, Ami 8, Mehari	C 32 S	600 S	-	0,6
America, Super America, Carga, Gringa (IES)	C 32 S	600 S	-	0,6
AX 1.4 Allure	RFC 52 LS	RFC 58 LS	F54	0,8
AX 1.4 GTi	RFC 52 LS	RFC 58 LS	F54	0,8
BERLINGO Furgon y Multispace - 1,4 y 1,8	RFC 58 LZK	RFC 62 LS	F54	0,9
BX 1.9 GTi	RFC 52 LS	RFC 62 LS	F54	0.8
C3 - 1,4i - 16V (ET3)	RWC 52 HSK	-	-	0,9
C3 - 1,4i - 8V	RFC 58 LZK	RFC 62 LS	F54	
C3 - 1,6i - 16V (TU5-JP4)	RFN 58 HZ	RFN 58 HZ	-	0,9

C4 - 1,4i - 16V (ET3)	RWC 52 HSK	-	-	0,9
C4 - 1,6i - 16V (TU5-JP4)	RFN 58 HZ	RFN 58 HZ	-	0,9
C4 - 2,0i - 16V (EW10J4-L4)	RFN 52 HZ	RFN 58 HZ	RFN 52 HZ3A	0,9
C5 - 1,8 i - 16 V - Motor EW7J4 (82/112)	RFN 52 HZ	RFN 58 HZ	RFN 52 HZ3A	0,9
C5 - 2,0 i - 16 V - Motor EW10J4-L4(RFR)(100/135)	RFN 52 HZ	RFN 58 HZ	RFN 52 HZ3A	0,9
C5 - 3,0 V6 - 24 V - Motor ES9J4 (XFZ) (143-194)	RFN 52 LZ	RFC 62 LS	F54	0,9
CX 2.0 Athena	C 62 LJS	755 LJS	J65	0,6
CX 2400	C 32 S	600 S	N43	0,6
CX Pallas 2.0, 2.2, 2.4	C 32 S	600 S	N43	0,6
GS Especial/Pallas/X3, GSA Pallas/Club	C 62 LS	755 LS	L65	0,6
LNA 1.1	C 62 LJS	755 LJS	J65	0,6
SAXO - 1,1i X	RFC 58 LZK	RFC 62 LS	F54	0,9
SAXO - 1,4i VTS	RFC 58 LZK	RFC 62 LS	F54	0,9
Visa Club	C 52 LJS	755 LJS	J65	0,6
Xantia SX 1.8, 2.0	RFC 52 LS	RFC 62 LS	F54	0,8
XM 3.0 V6	RFC 52 LS	RFC 62 LS	F54	0,8
XSARA 2,0 i - 16V -Motor EW10J4-L3 (99-135)	RFN 52 HZ	RFN 58 HZ	RFN 52 HZ3A	0,9
XSARA PICASSO 1,6 i - 16V	RFC 58 LZK	RFC 62 LS	F54	0,9
XSARA PICASSO 2,0 i - 16V-Mot.EW10J4-L3	RFN 52 HZ	RFN 58 HZ	RFN 52 HZ3A	0,9
XSARA SX 1,6 16V-Motor TU5JP (NFZ)	RFC 58 LZK	RFC 62 LS	F54	0,9
XSARA SX 1,6 i - 16V-Motor TU5JP4-I4	RFN 52 HZ	RFN 58 HZ	RFN 52 HZ3A	0,9
XSARA VTS 2,0 i - 16V -Motor XU10J4RS-L3	RFC 58 LZK	RFC 62 LS	F54	0,9
DODGE				
Coronado (autom., manual), Polara, GT, RT, GTX (6 Cil.)	C 30 LS	600 LS	-	0,8
GTX 8 cil. (rosca Ø 14 mm), Rural, SPL	C 32 LS	600 LS	-	0,8
1500 y 1.8, Rural, GT 90	C 52 LS	755 LS	L65	0,6
D 100, D 200 (Alc. Rosca 3/8")	-	500 C	-	0,7
D 100, D 200 (Alc. Rosca 3/4")	C 30 LS	600 LS	-	0,7
FIAT				
125 - TODOS	C 52 LS	755 LS	L65	0,7
128 - TODOS	C 52 LS	755 LS	L65	0,6
133 B / L / T	C 52 LS	755 LS	L65	0,6
147 - TODOS	C 52 LS	755 LS	L65	0,6
1500 TODOS	C 32 LS	755 LS	L65	0,6
600 (rosca corta) - 800 Coupe	C 32 S	600 S	N43	0,6
600 (rosca larga)	C 32 LS	707 LS	-	0,6

Barchetta 1.8 i 16V	RFC 58 LZ 2	RFC 62 LS	F54	-
Brava 1.6 MPI 16V	RFC 58 LZ 2	RFC 62 LS	F54	-
BRAVO	RFC 58 LZ2	RFC 62 LS	F54	1,0
BRAVO	RFC 58 LZ2	RFC 62 LS	F54	1,0
Coupé 2.0 i 16V (mot. 836.A3.000)	RC 72 LS	RC 82 LS	L87	0.8
Coupé 2.0 i 20V (5 cil.)	RFC 58 LZ 2	RFC 62 LS	F54	-
Duna 1.3, S, SC, SCX, 1.4 S, SC, SL - 1,5 y 1,6	C 52 LS	755 LS	L65	0,6
Duna CL, SCL, SCR	RC 52 LS	RC 62 LS	L65	0,6
Duna Weekend SCV (tipo 1.6 Brasil)	RC 52 LS	RC 62 LS	L65	0,6
Marea, Berlina y Familiar Mot. 1,6-1,8 y 2,0 - 20V	RFC 58 LZ2	RFC 62 LS	F54	1.0
Palio y Siena 1.0 MPI	RFC 52 LS	RFC 58 LS	F54	
Palio y Siena 1.6 MPI 16V	RFC 58 LZ 2	RFC 62 LS	F54	-
Palio y Siena 1.6 SPI 8V	RFC 52 LS	RFC 58 LS	F54	
Regatta - TODOS	C 52 LS	755 LS	L65	0,6
Stilo 1,8 - 16 V	RFN 58 LZ	RFC 62 LS	F54	0.9
Tempra 1.4, 1.6, 1.8, 2,0 ie. y Full 16V	RC 52 LS	RC 62 LS	L65	0,7
Tipo SP, SX 1.6 (carbu)	RC 62 LS	RC 72 LS	L65	0,7
Uno 1.5 (Brasil)	RC 52 LS	RC 62 LS	L65	0.6
Uno 1.6 CL	C 52 LS	755 LS	L65	0,6
Uno 1.6 R LE Jetronic	RC 52 LS	RC 62 LS	L65	0.6
Uno SL (tipo 1.4), SCL, SCX, y SCR	RC 52 LS	RC 62 LS	L65	0,6
DATSUN				
280 ZX	C 62 LS	755 LS	L65	0,9
FORD				
Bronco 3.0/4.0 V6	RC 52 LJS	RC 62 LJS	J65	1.0
Courier 1.4 i - 1,6i - 16V (mot. Zetec)	RC 62 HJS6	RC 62 HJSP	-	1.3
Escort 1.6 (mot. AE/CHT)	RFC 52 LS	RFC 58 LS	F54	0,7
Escort 1.6/1.8 (mot. AP)	C 52 LS	755 LS	L65	0,7
Escort 1.8 i 16V (mot. Zetec)	RC 62 HJSP	RC 62 HJSP	-	1.3
Escort Ghia 1.6	RFC 52 LS	RFC 58 LS	F54	0,7
Escort Ghia 1.6 (mot. AE)	C 52 LS	755 LS	L65	0.7
Escort Ghia 1.8	C 52 LS	755 LS	L65	0.7
Escort LX, SX	C 52 LS	755 LS	L65	0.7
Escort XR3, Cabriolet 1.8	RC 62 LS	RC 72 LS	L65	0,6
Explorer 3.0,- 4.0	RC 52 LJS	RC 62 LJS	J65	1,3
F - 100 Pick-up (mot. Max Econo)	C 52 LJS	755 LJS	J65	0,7

F-100 6 cil Max Econo	C 52 LJS	755 LJS	J65	0,8
Falcon 2.3 (4 cil.)	C 52 LJS	755 LJS	J65	0,7
Falcon Max Econo	C 52 LJS	755 LJS	J65	0,7
Fiesta 1.1	C 52 LJS	755 LJS	J65	0,8
Fiesta 1.3 CL, CLX (mot. JPC)	RFC 52 LS	RFC 58 LS	F54	0,7
Fiesta 1.3 i CLX (mot. JBC, J6B)	RC 52 LJS	RC 62 LJS	J65	1,1
Fiesta 1.4 i 16V (mot. Zetec)	RC 62 HJS6	RC 62 HJSP	-	1,3
Fiesta LX y LX Plus, 1,6 (mot. Zetec)	RC 62 HJS6	RC 62 HJSP	-	1,3
Focus 1,6 - 1,8 y 2,0 - 16 V. - Zetec	RC 62 HJSP	RC 62 HJSP	-	1,3
Galaxy 2.0 (mot. AP), 1.8 i, 2.0 i	RC 52 LS	RC 62 LS	L65	0,7
Granada 2.8, V6	RC 62 LS	RC 62 LS	L65	0,7
Ka - 1,0 y 1,6 ZETEC ROCAN	RC 62 HJSP	RC 62 HJSP	-	1,3
Ka - 1,0 y 1.3 i - Endura	RC 52 LJS	RC 62 LJS	J65	1,0
Mondeo 1.8 16V CLX, 2.0 16V Ghia	RC 62 HJS6	RC 62 HJSP	-	1,3
Mustang II 2.3, 2.8	C 62 LJS	755 LJS	J65	0,8
Orion 1.6 GL, GLi, 1.8 i GLX, 2.0 i Ghia	RC 52 LS	RC 62 LS	L65	0,7
RANGER - 4,0i - V8	RC 22 LJZ7	-	-	1,5
Ranger V6 4.0	RC 52 LJS	RC 62 LJS	J65	0,8
Ranger XL	RC 52 LJS	RC 62 LJS	L65	0,7
Sierra 2.3 CLX, Ghia, Ghia Rural GXL, Ghia S	C 52 LJS	755 LJS	J65	0,7
Sierra XR 4	C 52 LJS	755 LJS	J65	0,6
Taurus 2.0 L, GXL, Ghia, 2.3	C 52 LJS	755 LJS	J65	0,7
Taurus GT, Cupe/Cupe SP 5	C 52 LJS	755 LJS	J65	0,6
HONDA				
Accord 2.0/2.2 EX/LX	RFC 52 LS	RFC 58 LS	F54	1,1
Accord 2.3 i 16V	RFC 52 LS	RFC 58 LS	F54	1,1
Accord 3,0 V6 - EXL	RFC 52 LZDP5	-	F54	1,1
Civic 1.5 DX, LX, 1.6 EX	RFC 52 LS	RFC 58 LS	F54	1,1
Civic 1.6 VTI	RFC 52 LS	RFC 58 LS	F54	1,1
Civic - 1,8i - 16 V - VTI (B18C)	RFC 58 LS	RFC 62 LS	F54	1,1
CR-V - 2,4 - 4x2 y 4x4 - i VTEC - 16V - 2 A.L.	RFC 58 LZE5		F54	1,1
Prelude 2.2 i 16V DOHC	RFC 52 LS	RFC 58 LS	F54	1,1
Prelude 2.3	RFC 52 LS	RFC 58 LS	F54	1,1
HYUNDAI				
Accent GLS, GS, GT 1.5	RFC 52 LS	RFC 58 LS	F54	0,9
Atos y Atos Prime 1,0 GLS - 12 V - Mot. G4HC	RFC 52 LS	RFC 58 LS	F54	0,9

Coupé FX 2.0 i 16V	RFC 52 LS	RFC 58 LS	F54	0,9
Elantra 1.8 ie 16V	RC 52 LS	RC 62 LS	L65	1,1
Elantra New - 1,8 16 V - Mot. J2	RFC 52 LS	RFC 58 LS	F54	0,9
Excel 1.5	RC 52 LS	RC 62 LS	L65	0.8
Sonata 1.4, 2.0, 2.4, 3.0	RC 52 LS	RC 62 LS	L65	1,1
Sonata 3.0 V6	RC 32 LS	RC 52 LS	-	1,1
Sonata 2.0	RC 52 LS	RC 62 LS	L65	0,9
ISUZU				
Amigo	RC 52 LS	RC 62 LS	L65	1,1
Rodeo (mot. 4ZE1), Trooper (mot. 4ZE1)	RC 62 LS	RC 72 LS	L65	1,1
Rodeo 3.2 V6, Trooper 3.2 V6	RFC 52 LS	RFC 58 LS	F54	1,1
KIA				
Carens 1,8 Mot. T8D y T8DOHC	RFC 52 LS	RFC 58 LS	F54	1,1
Pride 1.3	RC 52 LS	RC 62 LS	L65	1,1
Sephia 1.6 GTX	RC 52 LS	RC 62 LS	L65	1,1
Clarus 2.0 i 16V	RFC 52 LS	RFC 58 LS	F54	1,1
Sportage 2.0 i 16V	RFC 52 LS	RFC 58 LS	F54	1,1
LADA				
Laika 1.6	C 52 LS	755 LS	L65	0,7
Niva, Nova	RC 52 LS	RC 62 LS	L65	0,7
Samara 1.5	RC 52 LS	RC 62 LS	L65	0,7
MAZDA				
121 1.1 (mot. B1)	RC 52 LS	RC 62 LS	L65	0,8
121 1.3 (mot. B3 cat)	RFC 52 LS	RFC 58 LS	F54	0,9
323 1.6 (mot. E6)	RC 52 LS	RC 62 LS	L65	1.0
323 1.6 16V GLX	RFC 52 LS	RFC 58 LS	F54	0,9
626 2.0 (mot. FE)	RC 52 LS	RC 62 LS	L65	0.9
626 2.0 16V GLX - Mot. FS DOHC	RFC 52 LS	RFC 58 LS	F54	0,9
626 2.5 - 24 V GLX - Mot. KL DOHC Cat.	RFC 58 LZ E	RFC 62 LS	F54	1,1
929 3.0 (mot. JE DOHC)	RFC 52 LS	RFC 58 LS	F54	0,9
B 1.6, 1.8, 2.6	C 52 LS	755 LS	L65	0,8
MPV 2.6, 3.0	RFC 52 LS	RFC 58 LS	F54	0,9
MX-3 1.8	RFC 52 LS	RFC 58 LS	F54	0,9
MX-5 1.6, 1.8 16V	RFC 52 LS	RFC 58 LS	F54	0,9
MX-5 Miata 1.6 16V	RFC 52 LS	RFC 58 LS	F54	0,9
MX-6 Coupe 2.0 16V	RFC 52 LS	RFC 58 LS	F54	0,9

MERCEDES BENZ				
190 E 1.8, 2.0, 2.3, 2.5 16V	C 52 LJS	755 LJS	J65	0,8
200 E 2.0 (mot. M102)	C 62 LJS	755 LJS	J65	0,8
200 Tipo 115/123 (mot. M115)	C 62 LS	755 LS	L65	0,8
220 CE, E, TE (mot. M111.960)	RFC 52 LS	RFC 58 LS	F54	0,8
230 E Tipo 123/124 (mot. M102)	C 52 LJS	755 LJS	J65	0,8
230 Tipo 114/115/124 (mot. 115), 230 G	C 62 LS	755 LS	L65	0,8
250 Tipo 114	C 62 LS	755 LS	L65	0,8
250 Tipo 123 (mot. M123.920)	C 52 LS	707 LS	L65	0,8
260 E, SE	C 52 LJS	755 LJS	J65	0,8
280, E, CE, GE, S, SE, SEL, SL, SLC (mot. M110)	C 62 LS	755 LS	L65	0,8
300 E, CE Tipo 124 (mot. M103)	C 52 LJS	755 LJS	J65	0,8
300 SE, SEL Tipo 126 (mot. M103)	C 52 LJS	755 LJS	J65	0,8
320 E	RFC 52 LS	RFC 58 LS	F54	0,8
350 SE, SEL, SL, SLC	C 62 LS	755 LS	L65	0,8
380, 450	C 62 LS	755 LS	L65	0,8
500 Tipo 107/126/463	C 62 LS	755 LS	L65	0,8
560 SE, SEC, SEL	C 62 LS	755 LS	L65	0,8
600 SEC, SL Tipo 129/140	RFC 52 LS	RFC 58 LS	F54	0,8
C 180	RFC 52 LS	RFC 58 LS	F54	0,8
Clase A - 140 / 160 / 190	RFC 58 LZ 3X	RFC 62 LS	F54	0,9
SLK	RFC 58 LZ3EX	RFC 62 LS	F54	0,9
SLK	RFC 58 LZ3EX	RFC 62 LS	F54	0,9
VITO	RFC 42 LZ2E	RFC 52 LS	F54	1,0
MITSUBISHI				
3000 GT 3.0	RFC 52 LS	RFC 58 LS	F54	0,9
Colt 1200, 1400	C 52 LS	755 LS	L65	0,8
Colt 1.5 (mot. 4G15)	RC 52 LS	RC 62 LS	L65	0,8
Colt 1.6 16V GLXI	RC 62 LS	RC 72 LS	L65	0,9
Eclipse 2.0 (mot. 4G63/T)	RC 52 LS	RC 62 LS	L65	0,8
Galant 1.6, 2.0	RC 62 LS	RC 72 LS	L65	0,8
Lancer 1.5 (mot. 4G15)	RC 62 LS	RC 72 LS	L65	0,8
Lancer 1.6 16V GLXI	RC 62 LS	RC 72 LS	L65	0,9
Mirage 1.8	RFC 52 LS	RFC 58 LS	F54	0,9
Montero (mot. 4G54)	C 52 LS	755 LS	L65	0,8
Montero (mot. 6G72 cat)	RC 52 LS	RC 62 LS	L65	1,1

Sapporo 1.6, 2.0	C 52 LS	755 LS	L65	0,8
Sigma 3.0 V6 24V	RFC 52 LS	RFC 58 LS	F54	0,9
Space Wagon 1.8 (mot. 4G93 MPI)	RFC 52 LS	RFC 58 LS	F54	0,9
Utilitarios :				
L100, L200, L300	C 52 LS	755 LS	L65	0,8
NISSAN				
200 SX (mot. Z20E)	RC 62 LS	RC 72 LS	L65	0,9
200 SX (mot. CA20E/ET)	RFC 52 LS	RFC 58 LS	F54	0,9
240 SX (mot. KA24DE)	RFC 52 LS	RFC 58 LS	F54	0,9
Bluebird 1.8 (mot. CA18N)	RC 62 LS	RC 72 LS	L65	0,9
Bluebird 2.0 (mot. CA20E)	RFC 52 LS	RFC 58 LS	F54	0,9
Maxima 3.0 (mot. VG30E)	RFC 52 LS	RFC 58 LS	F54	0,9
New Sentra 1.6 16V GXE	RFC 52 LS	RFC 58 LS	F54	0,9
NX 1.6	RFC 52 LS	RFC 58 LS	F54	0,9
Pathfinder 2.4 (mot. KA24E)	RFC 52 LS	RFC 58 LS	F54	0,9
Pathfinder 2.4 (mot. Z24i, Z24S)	RC 52 LS	RC 62 LS	L65	0,9
Pathfinder 3.0 (mot. VG30E, VG30i)	RFC 52 LS	RFC 58 LS	F54	0,9
Patrol 2.0	RFC 52 LS	RFC 58 LS	F54	0,9
Patrol 2.8 (mot. L28)	RC 62 LS	RC 72 LS	L65	0,9
Patrol 4.2	RC 52 LS	RC 62 LS	L65	0,9
Primera 2.0 16V GXE	RFC 52 LS	RFC 58 LS	F54	0,9
Sentra 1.6 (mot. GA16DE, GA16i)	RFC 52 LS	RFC 58 LS	F54	0,9
Sentra 1.6 (mot. E16, E16i, E16S)	RC 52 LS	RC 62 LS	L65	1,1
Serena 2.0 16V	RFC 52 LS	RFC 58 LS	F54	0,9
PEUGEOT				
106 1.1 i Max -	RFC 58 LZ K	RFC 62 LS	F54	0,9
106 1.4 i -	RFC 58 LZ K	RFC 62 LS	F54	0,9
106 1.6 i 16V S16	RFC 58 LZ K	RFC 62 LS	F54	0,9
205 1.4	FC 58 LS	RFC 62 LS	F54	0,8
205 1.4 i, 1.9 i (mot. XU9J1, desde 07/87)	RFC 52 LS	RFC 58 LS	F54	0,8
205 1.4 XS, 1.6 GTi (mot. XU5JA/B6E)	RFC 58 LZ K	RFC 62 LS	F54	0,8
205 1.9 GTi (mot. XU9JA)	RFC 58 LZ K	RFC 62 LS	F54	0,8
205 1.9 i (mot. XU9JA)	RFC 58 LZ K	RFC 62 LS	F54	0,8
206 - 1,4 (8 V.)	RFC 58 LZ K	RFC 62 LS	F54	0,9
206 - 1,4i - 16 V (Mot. ET3)	RWC 52 HSK	-	-	0,9

206 - 1,6 16 V	RFN 58 HZ	RFN 58 HZ	-	0,9
206 - 2,0 - 16 V	RFN 52 HZ	RFN 58 HZ	RFN 52 HZ3A	0,9
306 1.8 8V XN (mot. XU7JP)	RFC 52 LS	RFC 58 LS	F54	0,9
306 1.8 i 16V XR, XR Familiar, XT (mot. XU7JP4)	RFC 58 LZ K	RFC 62 LS	F54	0,9
306 1.8, SR, XR, XT, Cabriolet (mot. XU7JP)	RFC 52 LS	RFC 58 LS	F54	0,9
306 2.0, ST, XSi, Griffe, Cabriolet (mot. XU10J2C)	RFC 58 LZ K	RFC 62 LS	F54	0,9
307 1,4i - 16V - (Mot.ET3)	RWC 52 HSK	-	-	0,9
307 1,6 i 16 V. 2	RFN 58 HZ	RFN 58 HZ	-	0,9
307 2,0 i 16 V. 2	RFN 52 HZ	RFN 58 HZ	RFN 52 HZ3A	0,9
404 - Todos	C 52 LS	755 LS	L65	0.6
405 1.6 GL	RFC 58 LZ K	RFC 62 LS	F54	0,9
405 1.9 (mot. XU92C)	RFC 58 LZ K	RFC 62 LS	F54	0,9
405 2.0 i SRI (mot. XU10J2C)	RFC 58 LZ K	RFC 62 LS	F54	0,9
405 2.0 Mi 16	RFC 58 LZ K	RFC 62 LS	F54	0,9
405 GR, SR	RFC 52 LS	RFC 58 LS	F54	0,8
405 GRi	RFC 58 LZ K	RFC 62 LS	F54	0,9
406 1.8 i 16V ST (mot. XU7JP4)	RFC 58 LZ K	RFC 62 LS	F54	0,9
406 2.0 i y 2,2 16V SV (mot. XU10J4R)	RFC 58 LZ K	RFC 62 LS	F54	0,9
406 Coupé 3.0 V6 24V	RFN 52 LZ	RFC 62 LS	F54	0,9
407 Sport 2,2	RFN 52 HZ	RFN 58 HZ	RFN 52 HZ3A	0,9
407 Sport V6 - Triptronic	RFN 52 HZ3A	-	RFN 52 HZ3A	0,9
504 1.6, 1.8, 2.0	C 52 LS	755 LS	L65	0.6
504 1.8, 2.0 E, SE	C 52 LS	755 LS	L65	0.6
504 2.0 8V SL y G (carb.)	C 52 LS	755 LS	L65	0.6
504 GR, GR II, SR	C 52 LS	755 LS	L65	0.6
504 SRX, TN, SES, XS	C 52 LS	755 LS	L65	0.7
505 2.0 (mot. XN...)	C 52 LS	755 LS	L65	0.6
505 2.2 (exempto Turbo)	C 52 LJS	755 LJS	J65	0.6
505 2.2 SRi	C 52 LJS	755 LJS	J65	0.7
505 SRi (excepto 2.2), SR, GR, Familiar, Aut. Injection	C 52 LS	755 LS	L65	0.7
604 2.7, 2.8, Ti	C 52 LJS	755 LJS	J65	0,6
604 SL, Ti, STi	C 52 LJS	755 LJS	J65	0,6
605 2.0	RFC 52 LS	RFC 58 LS	F54	0,6
605 2.0 i	RFC 52 LS	RFC 58 LS	F54	0,6
605 Turbo 16V	RFC 42 LZ 2E	RFC 52 LS	F54	0,6
605 V6, V6 24V (mot. ZPJ, ZPJ4)	RFC 58 LZ K	RFC 62 LS	F54	0,9

607 3,0 V6, 24V, 4	RFC 58 LZ K	RFC 62 LS	F54	0,9
806 2.0 8V ST	RFC 42 LZ 2E	RFC 52 LS	F54	-
Utilitarios :				
Partner 1,4i	RFC 58 LZK	RFC 62 LS	F54	0,9
Partner 1,8	RFC 58 LZ K	RFC 62 LS	F54	0,9
404 T4B, 504 T6B	C 52 LS	755 LS	L65	0.7
RENAULT				
Clio 1,6 - Mot. C3L	C 52 LS	755 LS	L65	0,9
Clio 1.4 RT - Mot. E7J-	FC 52 LS	RFC 62 LS	F54	0.8
Clio 1.6 i 8V RL, RN, RT (mot. K7M)	RFC 58 LZ 2E	RFC 62 LS	F54	0,8
Clio 1.8 i - RN, RT - Mot. F3P	RC 52 LS	RC 62 LS	L65	0.9
Clio 1.8 i 16V - Mot. F7P -	RFC 52 LS 3	RFC 58 LS	F54	0.9
Clio II - 1,2 16V.	RFC 58 LZ 2E	RFC 62 LS	F54	-
Clio II - 1,6 16 V.	RFC 58 LZ 2E	RFC 62 LS	F54	-
Clio II - SPORT - 1,6 - 16 V. Mot. K4M-748	RFC 58 LZK	RFC 62 LS	F54	0,9
Clio II - 1,2i - (Mot. D7F-Euro)	RFC 58 LZP	-	F54	0,9
Clio II - 1,2i - (Mot.D4F)	RWC 52 HSK	-		0,9
Clio III - 1,2i - 16V - (Mot. D4F)	RWC 52 HSK	-		0,9
Clio III - 1,4i - 16V - (Mot. K4J)	RFN 58 LZ	RFC 62 LS	F54	0,9
Clio III - 1,6i - 16V - (Mot. K4M)	RFN 58 LZ	RFC 62 LS	F54	0,9
Fuego 2.0, GTX, GTX Auto., TX, TX Auto.	C 52 LJS	755 LJS	J65	0.6
Fuego 2.2 GTX, GTA	C 52 LJS	755 LJS	J65	0.7
Fuego Turbo	-	805 LP	L65	0,6
IKA (mot. Continental)	-	500 C	-	0.6
Kangoo - 1,6 i - RL - 16 V (Mot.K4M)	RFC 58 LZK	RFC 62 LS	F54	0,9
Kangoo 1.2 i RL - (Mot. D7F)	RFC 58 LZ 2E	RFC 62 LS	F54	-
Kangoo Express - 1,6 i - RL - (Mot.K7M)	RFC 58 LZ 2E	RFC 62 LS	F54	-
Laguna 2.0 - 16V RXT (mot.N7Q)	RFC 52 LS 3	RFC 58 LS	F54	-
Laguna 2.0 8V RT (mot. F3R)	RC 52 LS	RC 62 LS	L65	0.9
Laguna 3.0 - V6 - 24V RXT (mot.Z7X)	RFC 58 LS3	RFC 62 LS	F54	-
Logan 1,4i y 1,6i - Mot. K7J - K7M	RFC 58 LZ2E		F54	0,9
Mégane 1.6 - 16V - RT (mot. K4M)	RFC 58 LZK	RFC 62 LS	F54	0,9
Mégane 1.6 - 8V - RT (mot. K7M)	RFC 52 LS	RFC 58 LS	F54	0,9
Mégane 2.0 - 16V - RT, RXE (mot. F7R)	RFC 58 LS3	RFC 62 LS	F54	-
Mégane 2.0 8V RT, RXE (mot. F3R)	RC 52 LS	RC 62 LS	L65	0.9
Mégane Cabriolet 2.0 16V (mot. F7R)	RFC 58 LS3	RFC 62 LS	F54	-

Mégane Cabriolet 2.0 8V (mot. F3R)	RC 52 LS	RC 62 LS	L65	0.9
Mégane Coupé 1,6 - 16V (mot. K4M)	RFC 58 LZK	RFC 62 LS	F54	0,9
Mégane Coupé 2.0 - 16V (mot. F7R)	RFC 58 LS3	RFC 62 LS	F54	-
Mégane Coupé 2.0 8V (mot. F3R)	RC 52 LS	RC 62 LS	L65	0.9
Mégane Scenic 2,0 - 16 V - (Mot. F4R)	RFC 58 LZK	RFC 62 LS	F54	0,9
Mégane Scenic RT - 1,6i - 16V - (Mot. K4M-K7M)	RFC 58 LZK	RFC 62 LS	F54	0,9
Mégane Scenic RXE -2,0 - 8V - (Mot.F3R)	RC 52 LS	RC 62 LS	L65	0.9
R11 (excepto 1.7) GTL, TL, TS, TXE	C 52 LS	755 LS	L65	0.6
R12 L, TL, GTL, TS, Break GTS	C 32 S	600 S	N43	0.6
R18 1.4	C 52 LS	755 LS	L65	0.6
R18 1.6 (exepcto Turbo)	C 52 LS	755 LS	L65	0.6
R18 2.0	C 52 LJS	755 LJS	J65	0.7
R18 2.2 LX, GTX 2, TXE	C 52 LJS	755 LJS	J65	0.7
R18 2.2 TX, GTX, Break	C 52 LJS	755 LJS	J65	0.7
R19 1.7	C 52 LS	755 LS	L65	0.8
R19 1.7 RT (carbu)	C 62 LS	755 LS	L65	0.8
R19 1.8 i 16V	RFC 58 LZ 2E	RFC 62 LS	F54	-
R19 1.8, i	C 52 LS	755 LS	L65	0.9
R19 GTS, TS, TSE	FC 52 LS	RFC 62 LS	F54	0,9
R20 1.6 GTL, L, TL	C 62 LS	755 LS	L65	0,6
R20 2.0/2.2 GTS, RX, TI, TXE	C 62 LJS	755 LJS	J65	0.7
R21 2.0, 2.2, Nevada, 2.2 i	C 52 LJS	755 LJS	J65	0.7
R21 2.2 (J6T, J7T-754/755)	C 62 LJS	755 LJS	J65	0.9
R21 2.2 i (mot. J7T-756)	C 52 LJS	755 LJS	J65	0.9
R21 Turbo	C 52 LJS	755 LJS	J65	0.6
R30	C 62 LJS	755 LJS	J65	0.6
R4, R6	C 32 S	600 S	N43	0.6
R5 0.8	C 32 S	600 S	N43	0.6
R5 1.1	C 42 S	705 S	-	0.6
R5 Super 5 GT Turbo S	-	805 LP	L65	0,6
R5 Super 5 GTL	C 52 LS	755 LS	L65	0.6
R9 (excepto 1.7) GTL, TSE, TXE, RN, RL	C 52 LS	755 LS	L65	0.6
R9/11 - 1.1, 1.2, 1.4 (exepcto Turbo)	C 52 LS	755 LS	L65	0.8
R9/11 - 1.4 TS, 1.6 GTE, TXE	C 52 LS	755 LS	L65	0.6
R9/11 - Turbo	-	805 LP	L65	0.6
Rambler Torino (mot. Tornado)	C 32 S	600 S	N43	0.6

Safrane 3.0 V6	RFC 58 LZ 2E	RFC 62 LS	F54	-
TORINO IKA (mot. Tornado)	C 32 S	600 S	N43	0,6
Twingo (mot. C3G, 44 kw/55 ch)	RC 32 LS	RC 52 LS	-	0,9
Twingo 1,2 8V.-(Mot. D7F)	RFC 58 LZ 2E	RFC 62 LS	F54	-
Twingo 1,2i - 16V - (Mot.D4F)	RWC 52 HSK	-		0,9
Utilitarios :				
Jeep 1000, Estanciera (mot. Tornado)	C 32 S	600 S	N43	0,6
Jeep, Estanciera, Rambler (mot. Continental)	-	500 C	-	0,6
R4 Pick-up, Furgon	C 32 S	600 S	N43	0,6
Trafic 1.4, 1.6	C 52 LS	755 LS	L65	0,6
Trafic 2.0 (mot. J5R-..., 829-...)	C 52 LS	755 LS	L65	0,9
Trafic 2.2 (mot. J7T-780)	C 52 LJS	755 LJS	J65	0,8
ROVER				
214 1.4 16V	RFC 52 LS	RFC 58 LS	F54	0,9
216 1.6 16V	RFC 52 LS	RFC 58 LS	F54	1,1
220 GTi	RFC 52 LS	RFC 58 LS	F54	0,8
414 1.4 16V GSi	RFC 52 LS	RFC 58 LS	F54	0,8
416 1.6 GTi 16V	RFC 52 LS	RFC 58 LS	F54	1,1
420 2.0, Turbo	RFC 52 LS	RFC 58 LS	F54	0,8
618 Si 16V	RFC 52 LS	RFC 58 LS	F54	0,9
620 2.0 i 16V GSI Lux (mot. F20 A/A4)	RFC 52 LS	RFC 58 LS	F54	1,1
820 Si	RFC 52 LS	RFC 58 LS	F54	0,8
Discovery 2.0	RFC 58 LS	RFC 58 LS	F54	0,9
Range Rover 4.2 i V8	RC 32 LS	RC 52 LS	-	0,8
SAAB				
900 i (exopto 16V, Turbo)	C 62 LS	755 LS	L65	0,6
9000 2.3 16V	RFC 52 LS	RFC 58 LS	F54	1,0
SEAT				
Alhambra 2,0	RFC 58 LZ3EX	RFC 62 LS	F54	0,9
Cordoba 1.6 i, - 1.8 i y 2,0i	RC 58 LZ 3EX	RC 62 LS	L65	-
Ibiza 1.4 i	RC 58 LZ 3EX	RC 62 LS	L65	-
Ibiza 1.6 i (mot. ABU)	RC 52 LS	RC 62 LS	L65	1,1
Ibiza 1.8 i (exopto 16V)	RC 58 LZ 3EX	RC 62 LS	L65	-
Ibiza 2.0 i (mot. AGG, 2E)	RC 58 LZ 3EX	RC 62 LS	L65	-
Inca 1,6i - 8V -	RC 52 LS	RC 62 LS	L65	1,1
Leon 1,6 - 8 V -	RC 58 LZ 3EX	RC 62 LS	L65	-

Leon 1,8 - 20V -	RC 58 LZ 3EX	RC 62 LS	L65	-
Toledo 1.6 (mot. ABN, EZ)	RC 52 LS	RC 62 LS	L65	1,1
Toledo 1.8 i (mot. ABS, ADZ)	RC 58 LZ 3EX	RC 62 LS	L65	-
Toledo 2,3 - V5 - (Mot. AGZ)	RFC 42 LZ4E	RFC 62 LS	F54	-
Toledo 2.0 i (mot. AGG, 2E)	RC 58 LZ 3EX	RC 62 LS	L65	-
SKODA				
Felicia 1.3 GLX	RFC 52 LS	RFC 58 LS	F54	0,8
SUBARU				
Impreza 1.6, 1.8	RFC 52 LS	RFC 58 LS	F54	1,1
Impreza 2,5i - 16V - (Mot.EJ25)	RFC 52 LS	RFC 58 LS	F54-5	1,1
Justy 1.2	RC 62 LS	RC 72 LS	L65	1.1
Legacy 1.6, 1.8, 2.0, 2.2 16V	RFC 52 LS	RFC 58 LS	F54	1,1
SUZUKI				
Baleno 1.3 i, 1.5 i, 1.6 i	RFC 52 LS	RFC 58 LS	F54	0,8
Baleno 1.8 i 16V	RFC 52 LS	RFC 58 LS	F54	1,1
Samurai, Vitara 1.6	RC 52 LS	RC 62 LS	L65	0.8
Swift 1.0, 1.3 SA cat	RC 62 LS	RC 72 LS	L65	0.8
Swift 1.6, Vitara 1.6 4V	RFC 52 LS	RFC 58 LS	F54	0,8
TOYOTA				
Carina II 2.0 (mot. 3S-F, 3S-FE)	RFC 58 LZK	RFC 62 LS	F54	1.1
Celica 2.0 (mot. 3S-FE, 3S-GTE)	RFC 58 LZK	RFC 62 LS	F54	1.1
Celica, Cressida, Corolla, Carina II 2.0 (mot. 2SE)	C 52 LS	755 LS	L65	0.8
Corolla 1.6 (mot. 4AFE), 4/4	RFC 58 LZK	RFC 62 LS	F54	1.1
1.6 i 16V	RFC 58 LZK	RFC 62 LS	F54-5	1.1
Corolla 1.8 (mot. 3TC)	RC 52 LS	RC 62 LS	L65	0.8
Corona 2.0 (mot. 2SC, 2SEC)	RC 52 LS	RC 62 LS	L65	0.8
Hi-Ace 2.0 (mot. 1RZ)	RC 52 LS	RC 62 LS	L65	0.8
Hi-Lux, 4/4 (mot. 20R)	RC 52 LS	RC 62 LS	L65	0.8
Land Cruiser 2.4 (mot. 22R)	RC 52 LS	RC 62 LS	L65	0.8
Land Cruiser 4.0 i (mot. 3FE)	RC 52 LS	RC 62 LS	L65	1.1
RAV-4 2.0 i 16V (mot. 3S-FE)	RFC 58 LZK	RFC 62 LS	F54	1.1
VOLKSWAGEN				
1500, Carat 1.8, M 1.8, Rural 1.8	C 52 LS	755 LS	L65	0,7
Beetle 2,0i ,	RFC 58 LZ 3EX	RFC 62 LS	F54	-
Bora - 1,8 Ti - Turbo - 20V	RFC 58 LZ 3EX	RFC 62 LS	F54	-
Bora 2.0 i Comfort, Sport, Variant	RFC 58 LZ 3EX	RFC 62 LS	F54	-

Carat CD, GS	RC 52 LS	RC 62 LS	L65	0,7
Escarabajo	C 32 S	600 S	N43	0,7
Gacel GL, GS 1.6, 1.8, Saveiro	C 52 LS	755 LS	L65	0,7
Gol 1.3 (mot. Aire)	C 52 LS	755 LS	L65	0,7
Gol 1.6 (mot. AE, CHT)	RFC 52 LS	RFC 58 LS	F54	0,7
Gol 1.6 Mi, 1.8 Mi (mot. AP)	RC 52 LS	RC 62 LS	L65	0,7
Gol 1.6, Cli, Gli, 1.8, Cli, Gli (mot. AP)	RC 52 LS	RC 62 LS	L65	0,7
Gol 2.0 (mot. AP)	RC 52 LS	RC 62 LS	L65	0,7
Golf 1,8 Gti , 20V, Turbo	RFC 58 LZ 3EX	RFC 62 LS	F54	-
Golf 1,8i 8 V.	RC 52 LS	RC 62 LS	L65	0,7
Golf 2.0 GLX,	RFC 42 LZ 2E	RFC 52 LS	F54	-
Passat 1.6, L, LS	C 52 LS	755 LS	L65	0,7
Passat 1.8 i Turbo (mot. AEB)	RFC 58 LZ 3EX	RFC 62 LS	F54	-
Passat 2.0 16V (mot. 9A)	RFC 62 LZ 3EX	RFC 82 LS	F86	-
Passat 2.0 i 16V (mot. ABF)	RFC 58 LZ 3EX	RFC 62 LS	F54	-
Passat VR6 2.8	RFC 42 LZ 2E	RFC 52 LS	F54	-
Pointer 1.6 CLI, 1.8 GLI, 2.0 GTI	RC 52 LS	RC 62 LS	L65	0,7
Polo 1.6i Classic	RC 52 LS	RC 62 LS	L65	0,7
Polo 1.8 Classic	RC 52 LS	RC 62 LS	L65	0,7
Polo 1.8 Classic Mi (mot. AP)	RC 52 LS	RC 62 LS	L65	0,7
Quantum	C 52 LS	755 LS	L65	0,7
Senda 1.6	C 52 LS	755 LS	L65	0,7
Utilitarios :				
Caddy 1,6 i	RC 52 LS	RC 62 LS	L65	0,7
Furgon, Kombi, Microbus, Pick-up	C 32 S	600 S	N43	0,6
Saveiro 1.6 (mot. AE)	RFC 52 LS	RFC 58 LS	F54	0,7
Saveiro 1.8 (mot. AP), CI	RC 52 LS	RC 62 LS	L65	0,7
M 1.8	C 52 LS	755 LS	L65	0,7